## **KOLL COTTON CENTER**

4050 EAST COTTON CENTER BOULEVARD | PHOENIX, AZ



SEVEN MULTI-TENANT LIGHT INDUSTRIAL BUILDINGS TOTALING 225,608 SF • IRREPLACEABLE INFILL SKY HARBOR LOCATION



## LOCATION OVERVIEW



# **EXECUTIVE SUMMARY**

Cushman & Wakefield, as exclusive advisor, is pleased to offer the opportunity to acquire the 100% fee simple interest in Koll Cotton Center located at 4050 East Cotton Center Boulevard, Phoenix, AZ ("The Property"). This multitenant asset consists of seven light industrial buildings totaling 225,608 SF on 17.8 acres in the highly sought after Sky Harbor Airport submarket.

The Property is 96% leased with 4.0 years of weighted average lease term remaining. The average tenant size is 6,636 SF and current in-place rents are 19% below market. (Direct NNN asking rate in the submarket is \$1.21.) The staggered rent expiration schedule offers the opportunity to consistently grow the net operating income through annual rent escalations and marketrent renewal options.

The Sky Harbor Airport submarket has been the most robust and strongest performing industrial market in Metro Phoenix. This area is well-known due to its proximity to I-10, I-17, U.S. Route 60, and Loop 202. The Sky Harbor airport continues to experience record breaking rental growth due to strong tenant demand from corporate users in the logistics, distribution and e-commerce sectors.

Koll Cotton Center is strategically located less than 1 mile south of I-10 and minutes from a full diamond interchange at I-10 and Loop-202 to the southeast and Phoenix Sky Harbor International Airport to the northwest. In addition, the Property is less than 15 miles from the BNSF intermodal rail facility in Phoenix's West Valley. The Property provides excellent access to all points in the metro Phoenix and the greater California region via I-10 Freeway.

#### **INVESTMENT THESIS**

Koll Cotton Center is a rare investment opportunity to acquire a light industrial asset in the coveted Sky Harbor Airport submarket. Vacancy rates are at an all-time low throughout the Metro, but they are particularly low in the Sky Harbor Airport Submarket (3.6% as of Q1 2023). National and regional tenants are attracted to Phoenix because of its strategic west coast location, access to labor, numerous business and tax incentives and absence of natural disasters.

The below market rent opportunity coupled with the prime infill location of the asset, within a submarket with virtually no land availability, makes Koll Cotton Center a highly sought after investment opportunity.






# PROPERTY SUMMARY

| PROPERTY DETAILS           |  |  |  |
|----------------------------|--|--|--|
| Address                    | 4050 East Cotton Center<br>Phoenix, AZ |  |  |
| Parcel Number              | 123-06-028                             |  |  |
| Total Land Area            | 17.8 Acres                             |  |  |
| Total Land SF              | 775,431.00 SF                          |  |  |
| <b>Total Rentable Area</b> | 225,608 SF                             |  |  |
| Year Built                 | 2000                                   |  |  |
| Industrial Market          | Phoenix                                |  |  |
| Industrial Submarket       | Sky Harbor Airport                     |  |  |
| Water & Sewer              | City of Phoenix                        |  |  |
| Zoning                     | CP/BP; City of Phoenix                 |  |  |



| BUILDING FEATURES     |   |   |  |  |   |  |  |
|-----------------------|---|---|--|--|---|--|--|
| Building 1            | Building 2  | Building 3  | Building 4   | Building 5   | Building 6  | Building 7   |  |
| Masonry               | Masonry   | Masonry   | Masonry  | Masonry  | Masonry   | Masonry  |  |
| 26,630 SF             | 21,987 SF   | 28,788 SF   | 40,569 SF  | 24,342 SF  | 38,412 SF   | 44,880 SF  |  |
| 26,630 SF             | 21,987 SF   | 28,788 SF   | 36,503 SF  | 11,307 SF  | 22,898 SF   | 34,620 SF  |  |
| 16'                   | 16'   | 16'   | 18'  | 18'  | 18'   | 18'  |  |
| N/A                   | N/A   | N/A   | 2  | 4  | 12  | 11   |  |
| 114                   | 86  | 101   | 212  | 88   | 126   | 136  |  |
| 30' x 60' ; 30' x 80' | 40' x 90'   | 40' x 90'   | 40' x 100' ; 33' x 120'  | 40' x 120'   | 30' x 70' ; 30' x 90'   | 40' x 90'  |  |
| Wet                   | Wet   | Wet   | Wet  | Wet  | Wet   | Wet  |  |
| 1000A-277/480V 3p     | 1000A-277/480V 3p   | 800A-277/480V 3p  | 1600A-277/480V 3p  | 1200A-277/480V 3p  | 1600A-277/480V 3p   | 2000A-277/480V 3p  |  |
|                       | Building 1  Masonry  26,630 SF  26,630 SF  16'  N/A  114  30' x 60'; 30' x 80'  Wet | Building 1       Building 2         Masonry       Masonry         26,630 SF       21,987 SF         26,630 SF       21,987 SF         16'       16'         N/A       N/A         114       86         30' x 60'; 30' x 80'       40' x 90'         Wet       Wet | Building 1         Building 2         Building 3           Masonry         Masonry         Masonry           26,630 SF         21,987 SF         28,788 SF           26,630 SF         21,987 SF         28,788 SF           16'         16'         16'           N/A         N/A         N/A           114         86         101           30' x 60'; 30' x 80'         40' x 90'         40' x 90'           Wet         Wet         Wet | Building 1         Building 2         Building 3         Building 4           Masonry         Masonry         Masonry           26,630 SF         21,987 SF         28,788 SF         40,569 SF           26,630 SF         21,987 SF         28,788 SF         36,503 SF           16'         16'         18'           N/A         N/A         N/A         2           114         86         101         212           30' x 60'; 30' x 80'         40' x 90'         40' x 90'         40' x 100'; 33' x 120'           Wet         Wet         Wet         Wet | Building 1         Building 2         Building 3         Building 4         Building 5           Masonry         Masonry         Masonry         Masonry           26,630 SF         21,987 SF         28,788 SF         40,569 SF         24,342 SF           26,630 SF         21,987 SF         28,788 SF         36,503 SF         11,307 SF           16'         16'         18'         18'           N/A         N/A         N/A         2         4           114         86         101         212         88           30' x 60'; 30' x 80'         40' x 90'         40' x 90'         40' x 100'; 33' x 120'         40' x 120'           Wet         Wet         Wet         Wet | Building 1         Building 2         Building 3         Building 4         Building 5         Building 6           Masonry         Masonry         Masonry         Masonry         Masonry         Masonry           26,630 SF         21,987 SF         28,788 SF         40,569 SF         24,342 SF         38,412 SF           26,630 SF         21,987 SF         28,788 SF         36,503 SF         11,307 SF         22,898 SF           16'         16'         18'         18'         18'           N/A         N/A         2         4         12           114         86         101         212         88         126           30' x 60'; 30' x 80'         40' x 90'         40' x 100'; 33' x 120'         40' x 120'         30' x 70'; 30' x 90'           Wet         Wet         Wet         Wet         Wet         Wet         Wet |  |

# SITE PLAN



#### FOR MORE INFORMATION, PLEASE CONTACT

#### **INSTITUTIONAL SALES**

#### **WILL STRONG**

Executive Vice Chair +1 602 413 9991 will.strong@cushwake.com

#### KIRK KULLER

Senior Director +1 602 224 4456 kirk.kuller@cushwake.com

#### **MICKI STRAIN**

Managing Director +1 916 600 4653 micki.strain@cushwake.com

#### **MOLLY HUNT**

Associate +1 602 229 5944 molly.hunt@cushwake.com

#### **LEASING ADVISORS**

#### **JACKIE ORCUTT, SIOR**

Senior Vice President +1 602 735 1978 jackie.orcutt@cbre.com

#### JONATHAN TEETHER

Senior Associate +1 602 735 1929 jonathan.teether@cbre.com

#### **KENDALL SABA**

Account Manager +1 602 735 5509 kendall.saba@cbre.com

#### **DEBT ADVISORS**

#### **ROB RUBANO**

Vice Chair +1 310 595 2225 rob.rubano@cushwake.com

#### **BRIAN SHARE**

Executive Managing Director +1 310 595 2231 brian.share@cushwake.com

#### **FINANCIAL ANALYST**

#### **CALLAHAN CONWAY**

Senior Financial Analyst +1 602 229 5978 callahan.conway@cushwake.com

#### MARKETING CONTACT

#### STEPHANIE SACCENTE

Senior Marketing Lead +1 602 229 5966 stephanie.saccente@cushwake.com

### CUSHMAN & WAKEFIELD

#### CUSHMAN & WAKEFIELD NATIONAL INDUSTRIAL ADVISORY GROUP

#### **CENTRAL**

Jim Carpenter Mike Tenteris Adam Tyler Elizabeth Given

#### **MOUNTAIN WEST**

Will Strong Kirk Kuller Micki Strain Molly Hunt

#### WES.

Jeff Chiate Mike Adey Bryce Aberg Brad Brandenburg

#### **FLORIDA**

Mike Davis Rick Brugge Rick Colon Dominic Montazemi

#### SOUTHWEST

Jim Carpenter
Jud Clements
Robby Rieke
Taylor Starnes
Madeleine Supplee

#### **NORTHEAST**

Gary Gabriel Gerry Blinebury Kyle Schmidt Jon Carpenter Graham Savage

#### SOUTHEAS

Stewart Calhoun Casey Masters Ryan Bellows Drew Stanford

#### **DEBT TEAM**

Rob Rubano Brian Share Jeff Altenau John Alascio Gideon Gil

Click below for more information and insights from our National Industrial Advisory Group

www.cushmanwakefield.com/iag

#### ©2023 Cushman & Wakefield.

The material in this presentation has been prepared solely for information purposes, and is strictly confidential. Any disclosure, use, copying or circulation of this presentation (or the information contained within it) is strictly prohibited, unless you have obtained Cushman & Wakefield's prior written consent. The views expressed in this presentation are the views of the author and do not necessarily reflect the views of Cushman & Wakefield. Neither this presentation nor any part of it shall form the basis of, or be relied upon in connection with any offer, or act as an inducement to enter into any contract or commitment whatsoever. NO REPRESENTATION OR WARRANTY IS GIVEN, EXPRESS OR IMPLIED, AS TO THE ACCURACY OF THE INFORMATION CONTAINED WITHIN THIS PRESENTATION, AND CUSHMAN & WAKEFIELD IS UNDER NO OBLIGATION TO SUBSEQUENTLY CORRECT IT IN THE EVENT OF ERRORS.